

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
TETSUYO OHASHI, ET AL.) : Examiner: Daniel J. Colilla
Appl. No.: 10/822,658) : Group Art Unit: 2854
Filed: April 13, 2004) : Confirmation No.: 3144
For: BOTH-SIDE RECORDING APPARATUS) :
Patent No.: US 7,114,867 B2) :
Issued: October 3, 2006) April 15, 2008

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. However, the Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Mark A. Williamson/

Mark A. Williamson
Attorney for Patentees
Registration No. 33,628

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

MAW:eyw

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,114,867 B2

DATED : October 3, 2006

INVENTOR(S) : OHASHI, ET AL.

Page 1 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE:

At Item (56), References Cited, Foreign Patent Documents:

“JP 2001261181 A * 9/2001” should read --JP 2001-261181 A * 9/2001--.

“JP 2002127541 * 5/2002” should read --JP 2002-127541 A * 5/2002--.

“JP 2003002491 A * 1/2003” should read --JP 2003-002491 A * 1/2003--.

At Item (56), References Cited, Other Publications, “Machine translation of JP 20011261181” should read --Machine translation of JP 2001-261181--.

COLUMN 3:

Line 23, “life” should read --lift--.

Line 67, “flow charts” should read --flowcharts--.

COLUMN 4:

Line 26, “sheet” should read --sheets--.

COLUMN 5:

Line 8, “to” should read --to a--.

Line 13, “holder 23” should read --holder 23--.

Line 14, “FIG. 9” should read --FIG. 9--.

Line 17, “FIG. 3” should read --FIG. 3--.

Line 52, “FIG. 3” should read --FIG. 3--.

COLUMN 6:

Line 5, “heat” should read --head--.

Line 18, “such” should read --such an--.

COLUMN 11:

Line 26, “following” should read --following,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,114,867 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,114,867 B2

DATED : October 3, 2006

INVENTOR(S) : OHASHI, ET AL.

Page 2 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13:

Line 29, "allow to detect" should read --allow detecting--.

Line 40, "even it is" should read --even if it is--.

COLUMN 15:

Line 18, "mounted 48" should read --48 mounted--.

Line 50, "of" should read --of a--.

Line 55, "result" should read --result a--, and "an" should be deleted.

COLUMN 18:

Line 29, "operation" should read --operation,--.

Line 59, "rate etc." should read --rate, etc.,--.

COLUMN 21:

Line 18, "flow chart." should read --flowchart--.

Line 30, "reason" should read --reasons--.

COLUMN 22:

Line 41, "little" should read --little of--.

COLUMN 25:

Line 25, "the" should be deleted.

Line 34, "allows to rotate" should read --allows rotation of--.

Line 41, "and," (second occurrence) should be deleted.

COLUMN 26:

Line 18, "provides" should read --provides the--.

Line 58, "plant" should read --planet--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,114,867 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,114,867 B2

DATED : October 3, 2006

INVENTOR(S) : OHASHI, ET AL.

Page 3 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 27:

Line 20, "normal-direction" should read --normal direction--.

Line 44, "flow chart." should read --flowchart--.

Line 48, "flow" should read --flow---.

Line 51, "flow chart." should read --flowchart--.

COLUMN 30:

Line 13, "explained" should read --explained a--.

COLUMN 31:

Line 5, "completing" should read --completing a--.

Line 59, "reason" should read --reasons--.

COLUMN 34:

Line 32, "16E," should be deleted.

Line 37, "16E," (first occurrence) should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,114,867 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,114,867 B2

DATED : October 3, 2006

INVENTOR(S) : OHASHI, ET AL.

Page 4 of 4

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 35:

Line 9, "16E," (first occurrence) should be deleted.

Line 12, "allows to relieve" should read --allows relieving of--.

Line 16, "has" should read --has been--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,114,867 B2

No. of add'l. copies
@ 30¢ per page

